



HOLE IN CHASSIS:  $\phi 4.0$   
 CHASSIS THICKNESS:  $0.8$

PART NO	PACKAGE
FF-19	100